


GREASE INTERCEPTOR CERTIFICATION (Form A)

The City of Kingsport Wastewater Department is requiring that this grease interceptor certification be completed annually to verify that all components of the grease interceptor are present and in good working condition. Have a Kingsport certified grease waste hauler or plumber complete this form and submit to the City.

		Phone #:	
Address:City: Kingsport, TN. Zip C		ip Code	
		<u>PASS</u>	<u>FAII</u>
1. Interceptor completely emptied and clea	ned before inspection?		
2. There is access to all interceptor chambe			
3. Influent (inlet) T is attached and extends	s downward at least 2/3 depth of tank?		
4. Effluent (outlet) T is attached and extend	ds downward to within 12" of tank bottom?		
5. Effluent (outlet) T is made of non-collar bend (i.e. minimum schedule 40 PVC, et or grease to escape around edges?	tc.), and is secure, not allowing fats, oils		
6. Interceptor tank does Not have visible h			
7. Mid-wall baffle(s) is secure and operational?			
3. Interceptor maintaining structural integrity?			
O. No Sewer clean-out covers missing or damaged? Output Description:			
ail", the equipment has failed certification. mpleted, needs to be provided on the attache	N & RESPONSE: If the answer to any of the A statement of the plan of action to be taken, ed sheet under "Response Comments" (attach	with date to	o be
Fail", the equipment has failed certification. mpleted, needs to be provided on the attache plain corrective action if necessary): Inspector Certification — This grease inter	A statement of the plan of action to be taken, ed sheet under "Response Comments" (attach ceptor has PASSED FAILED of	with date to additional	o be sheets t
Fail", the equipment has failed certification. Impleted, needs to be provided on the attache plain corrective action if necessary): Inspector Certification — This grease inter I	A statement of the plan of action to be taken, ed sheet under "Response Comments" (attach receptor has PASSED FAILED of	with date to additional certification	o be sheets to on.
Tail", the equipment has failed certification. Impleted, needs to be provided on the attache plain corrective action if necessary): Inspector Certification — This grease inter I	A statement of the plan of action to be taken, ed sheet under "Response Comments" (attach receptor has PASSED FAILED of	with date to additional certification	o be sheets to
Tail", the equipment has failed certification. Impleted, needs to be provided on the attache plain corrective action if necessary): Inspector Certification – This grease interest. (print name of inspector) Certify that the above listed facility has an actan actan mined the interceptor and provided the actan (signature)	A statement of the plan of action to be taken, ed sheet under "Response Comments" (attach receptor has PASSED FAILED	with date to additional certification	o be sheets to on.
Tail", the equipment has failed certification. Impleted, needs to be provided on the attached plain corrective action if necessary): Inspector Certification — This grease interest. (print name of inspector) certify that the above listed facility has an an examined the interceptor and provided the action (signature) Facility Owner/Manager Certification	A statement of the plan of action to be taken, ed sheet under "Response Comments" (attach receptor has PASSED FAILED of	with date to additional certification	o be sheets t
Fail", the equipment has failed certification. Impleted, needs to be provided on the attache explain corrective action if necessary): Inspector Certification — This grease interest. I	A statement of the plan of action to be taken, ed sheet under "Response Comments" (attach receptor has PASSED FAILED of	with date to additional certification	o be sheets to on.



- A: Minimum 6", but not less than pipe diameter.
- B: Inlet pipe invert to be 2 ½" above liquid surface.
- C: Inlet pipe to terminate 2/3 depth of water level.
- D: 90 degree sweep, minimum size 6".
- E: 12" from floor to end of sweep F: 12" from floor to end of outlet pipe.
- G: Outlet pipe no smaller than inlet pipe, minimum of 4".
- H: Minimum depth of liquid capacity 42".
- J: Maximum distance from ceiling -6".

RESPONSE COMMENTS (required if "Fail" checked, identify problem, corrective action and provide planned date of corrective action)